



L475W/LS475W+ /LS500W/LS500W+ Firmware Update (For A0E/A0N/A0P Regions)

Content

Ver. 20180126X

1. Modify shut-off procedure when vehicle battery voltage is unstable when using DP4.
2. Fix time record logic caused by faulty real time clock. Faulty battery cause time to reset will no longer record as 2017/01/01. New recording will be 1 hour after last video before shutdown. (GPS equipped model will automatically adjust time when signal confirms)
3. New system default date starts from 2018/01/01
4. Cancel Time Lapse recording mode.
5. Add parking surveillance modes for different scenarios. Low-bit Rate Mode will record continuous parking surveillance videos in lower file size. Each clip is 10min at around 270MB. Parking time lapse will be 2 min per video, equals to 12 min in real world.
6. Add parking surveillance hot-key, press "menu" while recording will immediately enter preset parking surveillance mode. Press any key during parking surveillance will exit and return to normal recording.